CSI Country Wide Case Study Safety Strategy Discussion

Construction Safety Investigator

Instructions

The objective of this tool is to provide field supervisors with information to proactively engage workers and discuss safety related concerns that they may encounter. Safety discussions should not be limited to the subject above and should pertain to the activities that workers will be involved in that may have the potential for safety related exposures.

Case Day:

December 2007

Accident Type:

Rigging Accident - Debris Container

Relevant laws, rules and codes may include:

29CFR 1926.20(a)(1), (b)(2), (b)(3), 1926.21(b)(2), 1926.25, 1926.251

Case:

A 56 year old engineer was paralyzed from the waist down when he was hit by falling debris.

Accident Detail:

The engineer was employed by a Construction Manager (CM) hired to construct a high rise building complex. At the time of the incident, the engineer was in his office trailer reviewing plans.

The reinforced concrete subcontractor was utilizing the site's tower crane to lower debris containers from the construction floors to ground level for removal. The containers used were empty 55 gallon drums with holes burned in the sides (under the lid rig) for the rigging to be attached. They are raised to the floors, filled and then lowered back down and emptied.

While picking and lowering a container filled with scrap wood, rebar and other debris, the rigging (wire rope sling) attached to the steel drums tore through the lid ring allowing it to fall 28 stories and through the roof of the engineer's office trailer. The engineer was struck by the falling drum severely injuring him.

Reconstructive Safety Evaluation:

- · What are some of the possible causes of the accident being discussed?
- What actions could have been taken that might have prevented this accident from occurring?





Accident Scene Conclusion:

The investigation revealed that the concrete contractor was not using appropriate containers designed for the debris removal operations. The weight of the debris being hoisted was unknown which exceeded the drums capacity. In addition the workers assigned to attach the rigging to the containers (drums) were not properly trained or qualified riggers.

Preventive Safety Measures Include:

- All operations are preplanned using a Job Safety Task Analysis (JSTA) to ensure potential safety hazards associated with an
 operation are identified and appropriate steps are taken to eliminate or control them.
- Only properly trained and qualified employees are authorized to perform rigging operations.
- All loads to be hoisted are evaluated and are determined by a qualified person to fall within the safe working limits of the crane and the rigging used (to include skid pans or other containers).
- Ensure containers used to hoist materials or equipment are designed for and capable of performing the task without failure.

Attendance Roster			

Reference: This case is fictitious, and any resemblance to any persons, living or dead, is entirely coincidental. However, the type of accident described in this case summary happens all too often on construction sites.

Chubb. Insured.[™]

2

Chubb is the marketing name used to refer to subsidiaries of Chubb Limited, providing insurance and related services. For a list of these subsidiaries, please visit our website, www.chubb.com. Insurance is provided by ACE American Insurance Company and its U.S. based Chubb underwriting company affiliates. All products may not be available in all states. This communication contains product summaries only. Coverage is subject to the language of the policies as actually issued. Surplus lines insurance is sold only through licensed surplus lines producers. Loss control evaluations, reports, recommendations and services are made solely to assist the insurer in underwriting and loss control and are not to be construed as an added benefit for the insured, property owner or any other party (this may not apply if loss control services are purchased separately and specifically pursuant to a service agreement). Evaluation for any hazard or condition does not imply that it is covered under any policy. Chubb is the world's largest publicly traded property and casualty insurance group. With operations in 54 countries, Chubb provides commercial and personal property and casualty insurance, personal accident and supplemental health insurance, reinsurance and life insurance to a diverse group of clients. Chubb Limited, the parent company of Chubb, is listed on the New York Stock Exchange (NYSE: CB) and is a component of the S&P 500 index.